



# CONDICÃO ESPECIAL

## CE/SC n° 23 – 005

<b>Título:</b>	<b>Condição Especial Aplicável aos Equipamentos e Suprimento de Oxigênio</b>
<b>Title:</b>	<b>Special Condition for Oxygen Equipment and Supply</b>

---

**Aprovação:** Resolução nº 125, de 1º de dezembro de 2009, publicada no **Origem:** SAR  
Diário Oficial da União, N° 230, S/1, p. 35, de 2/12/2009

---

### APLICABILIDADE

Esta condição especial se aplica aos equipamentos e ao suprimento de oxigênio do avião Embraer EMB-505.

### CONDICÃO ESPECIAL

Esta condição especial complementa a seções 23.1441, 23.1443 e 23.1445 do RBHA 23, emenda 23-55.

#### “§ SC 23-005 Special Condition for Oxygen Equipment and Supply.

**SC RBHA 23.1441 In addition to the requirements of RBHA 23.1441(d), the following applies:**

**“A quick-donning oxygen mask system with a pressure-demand, mask-mounted regulator must be provided and immediately available for each flight crew member. It must be shown that each quick-donning mask can be placed on the face, from its ready position, properly secured, sealed and supplying oxygen upon demand, with one hand, within five seconds, and without disturbing eyeglasses or causing delay in proceeding with emergency duties.”**

**SC RBHA 23.1443 In addition to the requirements of RBHA 23.1443, the following applies:**

**“A continuous flow oxygen system must be provided for each passenger.”**

**SC RBHA 23.1445 In addition to the requirements of RBHA 23.1445, the following applies:**

**“If the flight crew and passengers share a common source of oxygen, a means to separately reserve the minimum supply required by the flight crew must be provided.”**